Sierra County Board of Supervisors' Agenda Transmittal & Record of Proceedings

MEETING DATE:	**TYPE OF AGENDA ITEM:**
May 5, 2020	☐Regular ☐Timed ☒Consent

DEPARTMENT: Public Works and Transportation
APPROVING PARTY: Tim H. Beals, Director
PHONE NUMBER: 530-289-3201

AGENDA ITEM: Approval of expenditure in the amount of $8,568.79 to Light Foot Truck Repair, Inc. for radioator replacement and and related parts and labor for Road Department vehicle #279, a water truck.

SUPPORTIVE DOCUMENTS ATTACHED: ☐Memo ☐Resolution ☐Agreement ☒Other
.

BACKGROUND INFORMATION: This is for necessary repairs in order to keep this equipment operational in the Road Department.

FUNDING SOURCE: 031 (Road)
GENERAL FUND IMPACT: No General Fund Impact
OTHER FUND:
AMOUNT: $8,600.00 N/A

ARE ADDITIONAL PERSONNEL REQUIRED?	**IS THIS ITEM ALLOCATED IN THE BUDGET?** ☒Yes ☐No
☐Yes, -- -- ☒No	**IS A BUDGET TRANSFER REQUIRED?** ☐Yes ☒No

SPACE BELOW FOR CLERK'S USE

BOARD ACTION:		
☐Approved ☐Approved as amended ☐Adopted ☐Adopted as amended ☐Denied ☐Other ☐No Action Taken	☐Set public hearing For: _____ ☐Direction to: _____ ☐Referred to: _____ ☐Continued to: _____ ☐Authorization given to: _____	Resolution 2020- _____ Agreement 2020- _____ Ordinance _____ Vote: Ayes: Noes: Abstain: Absent: ☐By Consensus

COMMENTS:

_____ _____
CLERK TO THE BOARD DATE

Lightfoot Truck Repair, Inc.
PO Box 7923
Auburn, CA 95604 US

PW - 613
031-3010-5241
V# 10853

INVOICE

INVOICE # 13256
DATE 04/09/2020
DUE DATE 04/30/2020
TERMS Due on receipt

BILL TO
Sierra County
Po Box 98
Downieville 95936
United States

SHIP TO
Truck# 279
1992 Freight. FTL
Vin# NP508913
Miles: 618,716

PLEASE DETACH TOP PORTION AND RETURN WITH YOUR PAYMENT.

TRUCK#
279

WO#
13301

DESCRIPTION	QTY	RATE	AMOUNT
Perform 90 Day BIT Vehicle Safety Inspection & Lube Chassis - Prepare Repair Estimate for needed repairs found & Also on List dropped off with Truck.	1	160.00	160.00
Chassis Grease	1	7.00	7.00T
Service labor hours	4	120.00	480.00
Front Axle Spring bushings & pins & hangers worn - Right front wheel seal leaking & contaminated brakes (Brake lining only 3/8" any way) - Supply parts to replace front axle Spring packs & Rear frame hangers & Pins - Replace U-Bolts & nuts & washers - Pull apart Right & Left side Brakes & remove Hubs & Clean & Inspect wheel bearings & Re assemble with new wheel seals & oil hub caps & Refill with new hub oil - Install new Brake shoes & hardware & Brake Drums - Adjust front axle Brakes after repair.			
Spring Pack	2	620.00	1,240.00T
Rear Frame Hanger	2	110.00	220.00T
Pin	6	20.00	120.00T
Side Bar	4	32.00	128.00T
U-Bolt - Nut - Washer	4	42.00	168.00T
Frt Brake Shoe Kit	2	62.00	124.00T
Front Brake Drums	2	265.00	530.00T
Wheel Seal	2	38.00	76.00T
Lucas Hub Oil	1	12.00	12.00T
Misc. Supplies & Hardware	1	15.00	15.00T
Service labor hours	3	120.00	360.00
Air system looses air rapidly with most obvious leaks in Dash From Parking Brake Valve & Cab Blower - Replace Park Brake Vale & Fittings & Repair air leak at Blower. After repairing these leaks more time may be needed to Inspect & Repair air leaks to get within legal limits & will have to update pricing.			
MV3 Park Brake Valve	1	254.00	254.00T
90 Deg. Fitting	1	8.00	8.00T

Thank you for your business. If you have any questions, please contact Larry at 916-849-0426 or email him at wrenchman2004@sbcglobal.net.

DESCRIPTION	QTY	RATE	AMOUNT
Drain Valve	1	16.00	16.00T
Misc. Fittings	1	45.00	45.00T
Service labor hours	8.50	120.00	1,020.00
Engine oil leak at Front Crankshaft Seal - Engine overheating - Pull Radiator & Send out for Rod Out & Inspection - Replace Front Crank Seal & P/S pump mounting gasket & All V-Belts - Repair broken bolt in A/C Comp. mount - Re Install Radiator & Hoses as needed & Replace Engine Thermostat & Refill with new Coolant.			
Front Crank Seal	1	66.00	66.00T
V-Belt	2	34.00	68.00T
V Belt	3	24.00	72.00T
Radiator	1	1,850.00	1,850.00T
Thermastat	2	50.00	100.00T
Gasket P/S Pump (Cumm)	1	6.00	6.00T
Antifreeze (Green/Gas Eng)	12	14.00	168.00T
Environmental Service Fee (Waste Antifreeze)	12	2.50	30.00T
Ataac Hose	2	57.00	114.00T
Clamp ATAAC Hose	1	12.00	12.00T
Service labor hours	4	120.00	480.00
Engine cooling Fan stays on all the time (Hoses connected together now) Replace Fan Solenoid & Re plumb air & Test Electric side & Test .			
Solenoid Valve Exh. Brake	1	168.00	168.00T
90deg. Fitting	2	5.00	10.00T
1/4" Plastic Air Line	16	0.95	15.20T
1/4" Plastic Wire Loom	16	0.60	9.60T
1/4" Wire Ties	15	0.45	6.75T

SUBTOTAL	8,158.55
TAX (7.25%)	410.24
TOTAL	8,568.79
BALANCE DUE	**$8,568.79**

Thank you for your business. If you have any questions, please contact Larry at 916-849-0426 or email him at wrenchman2004@sbcglobal.net.