

**Sierra County
Board of Supervisors'
Agenda Transmittal &
Record of Proceedings**

MEETING DATE: April 16, 2019	TYPE OF AGENDA ITEM: <input type="checkbox"/> Regular <input type="checkbox"/> Timed <input checked="" type="checkbox"/> Consent
--	---

DEPARTMENT: Department of Public Works and Transportation APPROVING PARTY: Tim H. Beals, Director PHONE NUMBER: 530-289-3201

AGENDA ITEM: Authorize road department expenditure in the amount of \$9,000 for needed repairs for the Goodyears Bar Road Maintenance Shop Generator.

SUPPORTIVE DOCUMENTS ATTACHED: Memo Resolution Agreement Other

BACKGROUND INFORMATION: Goodyear shop generator is blowing oil out of the main bearing seals and repairs or replacement of the generator is necessary. Repairs are estimated at \$8,092. Note that the quote from Holt of California is in the amount of \$11,352.00, however \$3,260 is for removal and reinstallation of the generator, which services are not needed, hence the \$8,092.00 amount.

FUNDING SOURCE: 031 (ROAD)
GENERAL FUND IMPACT: No General Fund Impact
OTHER FUND:
AMOUNT: \$9,000 N/A

ARE ADDITIONAL PERSONNEL REQUIRED? <input type="checkbox"/> Yes, -- -- <input checked="" type="checkbox"/> No	IS THIS ITEM ALLOCATED IN THE BUDGET? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No IS A BUDGET TRANSFER REQUIRED? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
--	---

SPACE BELOW FOR CLERK'S USE

BOARD ACTION: <input type="checkbox"/> Approved <input type="checkbox"/> Approved as amended <input type="checkbox"/> Adopted <input type="checkbox"/> Adopted as amended <input type="checkbox"/> Denied <input type="checkbox"/> Other <input type="checkbox"/> No Action Taken	<input type="checkbox"/> Set public hearing For: _____ <input type="checkbox"/> Direction to: _____ <input type="checkbox"/> Referred to: _____ <input type="checkbox"/> Continued to: _____ <input type="checkbox"/> Authorization given to: _____	Resolution 2019- _____ Agreement 2019- _____ Ordinance _____ Vote: Ayes: Noes: Abstain: Absent: <input type="checkbox"/> By Consensus
---	---	---

COMMENTS:

_____ CLERK TO THE BOARD	_____ DATE
-----------------------------	---------------

SIERRA CO ROAD DEPARTMENT
PO BOX 98 , DOWNIEVILLE CA

CUSTOMER NO.	QUOTE NO.	DATE	CONTACT
5217000	121378	4/3/2019	DEAN
PHONE NO.	FAX NO.	EMAIL	
(530) 289-3412		srdgoodshop@hughes.net	
MODEL	MAKE	SERIAL NO.	
3114	CATERPILLAR	6AF00496	
UNIT NO.	WO NO.	P.O. NO.	
NOTE			
PROPOSE TO FURNISH THE SUPPLIES, LABOR, PARTS, AND MATERIALS TO COMPLETE THE WORK DESCRIBED BELOW: THIS PROPOSAL ASSUMES THAT ALL WORK IS BEING COMPLETED DURING HOLT OF CALIFORNIA'S NORMAL BUSINESS HOURS, AND THAT ALL WORK WILL BE COMPLETED AT HOLT OF CALIFORNIA'S SHOP IN WEST SACRAMENTO CA.			

SEGMENT: 01 REMOVE & INSTALL ENGINE & GENERATOR (010 1021)
 NOTES:TRAVEL TO CUSTOMER SITE. DISCONNECT ENGINE SKID, LOAD CABLES, AND COMMUNICATION WIRES. USING HOLTS CRANE LOAD ENGINE/GENERATOR INTO TRAILER, AND TRANSPORT TO HOLTS SHOP. COMPLETE STEPS IN REVERSE TO REINSTALL ENGINE/GENERATOR.

Parts	Total Estimated Parts:	0.00
Labor	Total Flat Rate Labor:	2,640.00
Labor Summary		
Misc	Total Flat Rate Misc:	620.00
Segment 01 Total:		3,260.00

SEGMENT: 02 PM 2 ENGINE & GENERATOR (962 1021)
 NOTES:COMPLETE ANNUAL PM2 SERVICE AS PER THE ATTACHED "DESCRIPTION OF SERVICES".

Parts	Total Flat Rate Parts:	172.00
Labor	Total Flat Rate Labor:	620.00
Labor Summary		
Misc	Total Estimated Misc:	0.00

SEGMENT: 03 SERVICE ENGINE COOLING SYSTEM (912 1350)
NOTES:COMPLETE COOLING SYSTEM SERVICE AS PER THE
ATTACHED "DESCRIPTION OF SERVICES".

Parts	Total Flat Rate Parts:	342.00
Labor	Total Flat Rate Labor:	1,240.00
Labor Summary		
Misc	Total Estimated Misc:	0.00

Segment 03 Total: 1,582.00

SEGMENT: 04 REPAIR ENGINE OIL LEAK (023 9189)
NOTES:REPAIR OIL LEAKS AT THE OIL FILTER HOUSING, AND
OIL DRAIN VALVE. REPLACE FRONT, AND REAR
CRANKSHAFT SEALS. REPLACE ROCKER BOX GASKET, VALVE
COVER GASKET, AND OIL PAN GASKET. REPLACE GASKET,
AND SEALS BETWEEN THE INJECTION PUMP, AND
CYLINDER HEAD. ALL EXPOSED SURFACES WILL BE
INSPECTED, AND CLEANED. ALL DISTURBED GASKETS, AND
SEALS WILL BE REPLACED.

Parts	Total Flat Rate Parts:	318.00
Labor	Total Flat Rate Labor:	3,100.00
Labor Summary		
Misc	Total Estimated Misc:	0.00

Segment 04 Total: 3,418.00

SEGMENT: 05 SUPPLY AND INSTALL TURBOCHARGER (300 1052)
NOTES:REMOVE, AND SUBMIT OLD TURBOCHARGER FOR CORE
CREDIT (PROPOSAL DOES NOT INCLUDE THE CORE
CHARGE). INSTALL CAT REMAN TURBOCHARGER WITH NEW
SEALS, AND GASKETS. INSPECT FOR PROPER OPERATION.

Parts	Total Flat Rate Parts:	1,370.00
Labor	Total Flat Rate Labor:	310.00
Labor Summary		
Misc	Total Estimated Misc:	0.00

Segment 05 Total: 1,680.00

SEGMENT: 06

LOAD BANK TEST ENGINE (033 1000)
NOTES: COMPLETE A 2 HOUR LOAD TEST TO ENSURE PROPER
OPERATION.

Parts	Total Estimated Parts:	0.00
Labor	Total Flat Rate Labor:	620.00
Labor Summary		
Misc	Total Estimated Misc:	0.00

	Segment 06 Total:	620.00
	Total Segments:	11,352.00
SUB TOTAL (BEFORE TAXES)		11,352.00
TOTAL ESTIMATE		11,352.00

PO#: _____ Authorized Name: _____ (signature)

Date: _____ (print)

Thank you for this opportunity to serve your company

CONTACT INFORMATION:

Prepared by: Michael Roulet Phone: (916) 642-5426 Email: Mroulet@holtca.com Fax:

-
- This estimate will expire 90 days from the estimate date.
 - Price excludes Freight Charges, Operating Supplies/EPA Fees and Overtime.
 - Terms: Net 10th Prox.
 - Sales Taxes where applicable are not included with the above prices.
-

Terms and Conditions

Prices quoted are good for 90 days from the estimate date. Pricing includes the specific service listed and excludes freight, handling charges, applicable taxes, overtime, field service labor or additional services unless otherwise noted. All quotes are subject to credit approval.

Holt of California ("Holt") warrants its service labor for 12 months, 1,000 hours or 50,000 miles whichever occurs first from the date of last labor. The warranty does not apply if, in the opinion of Holt, the maintenance or operation is not reasonable and proper. Holt shall not be responsible for the removal or installation of any component installed by anyone other than Holt. All labor shall be provided during Holt 's normal working hours and any travel time, transportation or overtime shall be charged to the customer. In no event shall Holt be responsible, nor should the customer be entitled to any damages for loss of use of the equipment, productivity or any other consequential damages.